



### **AL SIDRA PH1 PROGRESS REPORT**

# **About the Project:**

Project Developer	Bin Faqeeh Real Estate Investment Company S.P.C.	
Title of Project	Al Sidra Villa	
Project Reference	BFALSIDRAPH1/08/0110-3110/2020	
Design & Supervision Consultant	MSCEB	
Interior Design Consultant	Horizon Interiors	
Main Contractor	Al Jameel Construction SPC	

## **About Progress Report:**

Title of Document	Progress Report of Al Sidra
Reporting Period	October 1, 2020 to October 31, 2020
Authors & project role	MSCEB
Date	November 8, 2020





#### **PHASE 1 VILLAS**

DESCRIPTION	PERCENTAGE (%) OF COMPLETION	REMARKS
Phase 1 Villas – 88 Nos	or domin element	
SUB STRUCTURE	1000/	
1. Filling of Class-3 Material and compaction	100%	Completed
Excavation for Grid beam and MEP services	100%	Completed
3. Blinding Concrete	100%	Completed
4. Formwork and reinforcement for grade slab	100%	Completed
5. Grade slab concrete	100%	Completed
SUPER STRUCTURE		
Ground Floor		
1. RCC for Column (GF)	100%	Completed
2. Block works for walls	100%	Completed
3. Internal Plastering for walls	83%	In Progress
First Floor		1
1. First Floor Slab Concrete	100%	Completed
2. RCC for Column (FF)	100%	Completed
3. Block work for walls	100%	Completed
4. Internal Plastering for walls	83%	In Progress
Second Floor		
Formwork and reinforcement for 2nd Floor Slab	100%	Completed
2. 2nd Floor Slab Concrete	100%	Completed
3. RCC for Column (2nd Floor)	100%	Completed
4. Block work for walls	100%	Completed
5. Internal Plastering for walls	81%	In Progress
Roof Floor		<del>-</del>
Formwork and reinforcement for Roof Slab	100%	Completed
2. Roof Slab concrete	100%	Completed
Waterproofing Works		
- Ground Floor (Toilet, Fry kitchen)	46%	In Progress
- 1st Floor (Terrace and Toilets)	46%	In Progress
- 2 <sup>nd</sup> Floor (Toilets and Laundry)	46%	In Progress
- Roof	57%	In Progress
False Ceiling Works		
- Ground Floor	50%	In Progress
- 1 <sup>st</sup> Floor	45%	In Progress
- 2 <sup>nd</sup> Floor	45%	In Progress
Internal Painting – Wal and Ceiling (1st Coat)		
- Ground Floor	22%	In Progress
- 1 <sup>st</sup> Floor	22%	In Progress
- 2 <sup>nd</sup> Floor	22%	In Progress





Floor Tile and Toilet Tile Works		
- Ground Floor	55%	In Progress
- 1 <sup>st</sup> Floor	37.5%	In Progress
- 2 <sup>nd</sup> Floor	50%	In Progress
External Plastering		
- Entire Villa	89%	In Progress
Aluminum Works		
- Ground Floor	21.5%	In Progress
- 1st Floor	21.5%	In Progress
- 2 <sup>nd</sup> Floor	21.5%	In Progress
Wood Works (Installation of Wooden Doors & Skirting	7)	
- Ground Floor	12%	In Progress
- 1st Floor	12%	In Progress
- 2 <sup>nd</sup> Floor	12%	In Progress
Vanity and Shower Threshold Marble		
- Ground Floor	12%	In Progress
- 1 <sup>st</sup> Floor	12%	In Progress
- 2 <sup>nd</sup> Floor	12%	In Progress
External Painting		
- Entire Villa (1st Coat)	15%	In Progress
- Entire Villa (Primer)	92%	In Progress





#### On-site Photos of Phase 1:



Aerial View Phase 1 Villas



Street View Phase 1 Villas





External Plastering preparation works in progress



External Painting works in progress







External Finishing works in progress



External Cladding Tile installation in progress







Wooden Doors & Skirting installation in progress



Internal Paint application in process



Toilet Shower Partition installation in progress