



SOMEWHERE RESIDENCES PROGRESS REPORT

About the Project:

Project Developer	Bin Faqeeh Real Estate Investment Company S.P.C.
Title of Project	Somewhere Residences
Project Reference	BFSR/03/0106-3006/2020
Consultant	Salah Al Kooheji Consulting Architects SPC
Main Contractor	Al Taitoon Contracting Co. WLL

About Progress Report:

Title of Document	Progress Report of Somewhere Residences	
Reporting Period	June 1, 2020 to June 30, 2020	
Date	July 7, 2020	





DESCRIPTION	PERCENTAGE (%) OF COMPLETION	REMARKS
MOBILIZATION AND PRELIMINARIES	50%	In Progress
PILING WORKS	100%	Completed
EXCAVATION AND FILLING	100%	Completed
SUB STRUCTURE WORKS	100%	Completed
CHDED CADITIONALD		
SUPER STRUCTURE		
1. Ground Floor	1000/	C l - t - d
a. Columns and Lift wall	100%	Completed
2. First Floor	1000/	C 1 . 1
a. First Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
3. Second Floor	4000/	0 1 1
a. Second Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
4. Third Floor		
a. Third Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
5. Fourth Floor		
a. Fourth Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
6. Fifth Floor		
a. Fifth Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
7. Sixth Floor		
a. Sixth Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
8. Seventh Floor		
a. Seventh Floor Slab	100%	Completed
b. Pool deck Slab	100%	Completed
c. Columns and Corewall	100%	Completed
9. Eight Floor		
a. Eight Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
10. Ninth Floor		
a. Ninth Floor Slab	100%	Completed
b. Columns and Shearwall	100%	Completed
11. Tenth Floor		•
a. Tenth Floor Slab	100%	Completed
b. Columns and Shearwall	100%	Completed





12. Eleventh Floor		
a. Eleventh Floor Slab	100%	Completed
b. Columns and Shearwall	100%	Completed
13. Twelveth Floor		
a. Twelveth Floor Slab	100%	Completed
EXTERNAL BLOCK WORK		
Ground Floor	20%	In Progress
First Floor	80%	In Progress
Second Floor	90%	In Progress
Third Floor	90%	In Progress
Fourth Floor Slab	90%	In Progress
Fifth Floor	90%	In Progress
Sixth Floor	70%	In Progress
INTERNAL BLOCK WORKS		
Ground Floor	20%	In Progress
First Floor	50%	In Progress
Second Floor	50%	In Progress
Third Floor	50%	In Progress
Fourth Floor	50%	In Progress
Fifth Floor	50%	In Progress
Sixth Floor	50%	In Progress
Seventh Floor	10%	In Progress
Eight Floor	10%	In Progress
Ninth Floor	10%	In Progress
Tenth Floor	10%	In Progress
Eleventh Floor	10%	In Progress
SUB STATION WORK		
Sub Station work	60%	In Progress
ELECTRICAL, FIRE ALARM AND ELV WORKS	14%	In Progress
PLUMBING WORKS	14%	In Progress
FIRE FIGHTING WORKS	14%	In Progress









Front View



Left View



Right View

Rear View










6th Floor – Block Work









11th Floor – Slab Reinforcement Work









11th Floor – Column Reinforcement Works



11th Floor – Shear Wall Concrete Work



11th Floor – Column Shuttering Work



12th Floor Slab Concrete Works