



SOMEWHERE RESIDENCES PROGRESS REPORT

About the Project:

Project Developer	Bin Faqeeh Real Estate Investment Company S.P.C.
Title of Project	Somewhere Residences
Project Reference	BFSR/02/0105-3105/2020
Consultant	Salah Al Kooheji Consulting Architects SPC
Main Contractor	Al Taitoon Contracting Co. WLL

About Progress Report:

Title of Document	Progress Report of Somewhere Residences
Reporting Period	May 1, 2020 to May 31, 2020
Date	June 8, 2020





DESCRIPTION	PERCENTAGE (%) OF COMPLETION	REMARKS
MOBILIZATION AND PRELIMINARIES	50%	In Progress
PILING WORKS	100%	Completed
EXCAVATION AND FILLING	100%	Completed
SUB STRUCTURE WORKS	100%	Completed
SUPER STRUCTURE		
1. Ground Floor		
a. Columns and Lift wall	100%	Completed
2. First Floor		<u> </u>
a. First Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
3. Second Floor		•
a. Second Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
4. Third Floor		•
a. Third Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
5. Fourth Floor		•
a. Fourth Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
6. Fifth Floor		
a. Fifth Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
7. Sixth Floor		
a. Sixth Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
8. Seventh Floor		
a. Seventh Floor Slab	100%	Completed
b. Pool deck Slab	100%	Completed
c. Columns and Corewall	100%	Completed
9. Eight Floor		
a. Eight Floor Slab	100%	Completed
b. Columns and Corewall	100%	Completed
10. Ninth Floor		
a. Ninth Floor Slab	100%	Completed
b. Columns and Shearwall	100%	Completed
11. Tenth Floor		
a. Tenth Floor Slab	80%	In Progress






EXTERNAL BLOCK WORK				
First Floor	80%	In Progress		
Second Floor	90%	In Progress		
Third Floor	90%	In Progress		
Fourth Floor Slab	90%	In Progress		
Fifth Floor	20%	In Progress		
INTERNAL BLOCK WORKS				
First Floor	20%	In Progress		
Second Floor	50%	In Progress		
Third Floor	50%	In Progress		
Fourth Floor	50%	In Progress		
Fifth Floor	50%	In Progress		
Sixth Floor	50%	In Progress		
Seventh Floor	10%	In Progress		
SUB STATION WORK				
Sub Station work	50%	In Progress		
ELECTRICAL, FIRE ALARM AND ELV WORKS	12%	In Progress		
PLUMBING WORKS	12%	In Progress		
FIRE FIGHTING WORKS	12%	In Progress		

On-site photos:

Elevations









Front View



Left View



Right View



Rear View









5th Floor – Block Work





9th Floor – Steel Works





9th Floor - Concrete Works



Somewhere



9th Floor – Column Steel Works



9th Floor – Shuttering Work



9th Floor – Shear Wall Shuttering



9th Floor – Column Concrete





9th Floor Slab – Curing Work